

September 4, 2003

CCN 44757

Ms. Kathleen E. Hain, Director Environmental Restoration Division U.S. Department of Energy Idaho Operations Office 850 Energy Drive, MS 1222 Idaho Falls, ID 83401-1563

CONTRACT NO. DE-AC07-99ID13727 - TRANSMITTAL OF THE NUMERICAL VALUE OF THE SOIL-TO-WATER PARTITION COEFFICIENT (K_d) FOR PLUTONIUM AT THE INEEL WHITE PAPER

Dear Ms. Hain:

This letter transmits nine copies of the subject document, three for you and your staff and three each for delivery to the Idaho Department of Environmental Quality and the U.S. Environmental Protection Agency. The white paper represents an independent review by outside Idaho National Engineering and Environmental Laboratory (INEEL) subject matter experts of the K_d values used at the INEEL for risk assessments. The report concludes that a soils K_d value for plutonium of 5,100 mL/g for WAG 7 is technically supportable and defensible based on several sources of evidence.

If you have any questions or comments, please contact Frank Webber at 526-8507 or Jean Holdren at 526-6901.

Sincerely,

John M. Schaffer, Project Director

earl Webby for

RWMC Completion Project

FLW:mp

Enclosures

cc: (w/o Enc.)

S. S. Crawford, INEEL, MS 3810

R. J. Hoyles, NE-ID, MS 1221

B. D. Shipp, INEEL, MS 3898

J. G. Snook, NE-ID, MS 1222

S. G. Stiger, INEEL, MS 3898

Ms. Kathleen E. Hain September 4, 2003 CCN 44757 Page 2

bcc:

(w/o Enc.)

M. P. Hodel, MS 3940

K. J. Holdren, MS 3920

B. G. Meagher, MS 3920

T. J. Meyer, MS 3920

E. R. Neher, MS 3930

F. L. Webber, MS 3920

ARDC Files, MS 3922 (w/Enc.)

Correspondence Control, MS 3106

OU 7-13/14 Project File (w/Enc.) J. M. Schaffer Letter File (JMS-105-03)

Uniform File Code: 6102

Disposition Authority: ENV1-h-1

Retention Schedule: Cutoff at submission of the final financial status report for the site, or after resolution of all issues, whichever is later. Destroy 10 years after cutoff with written approval from the EPA award official.

NOTE: Original disposition authority, retention schedule, and Uniform Filing Code applied by the sender may not be appropriate for all recipients. Make adjustments as needed.